



ILA-USMX JOINT SAFETY COMMITTEE

OSH Circular 2015-03 (10 March 2015)

Q: What's Missing From This Photo?



Concept: J. E.

A: An Injured Longshoreman

The operator of the toploader shown above was wearing his 3 point restraint [safety] belt. Without it, the result would have been a lot different. It makes sense... Click it!

Working Together For The Benefit Of All

ILA-USMX OSH Circulars are devised to reflect the best possible information and guidance, and are products of diligent research and the most up to date subject matter knowledge. Consequently, while the information contained herein is believed to be accurate, owing to a host of factors ILA-USMX can convey no direct or implied warranty relative to the reliance of parties upon content.